

ORX[®]

XP[®] METAL DETECTORS



Program & frequency used

Mineralisation strength

Ground balance's settings

Battery level (displays alternately)
Coil / Remote control / MI-6

Ground mineralisation index



Access to Options
Press 2 sec: ON / OFF

Change programs
Press 2 sec: SALT mode



Access to MENU
Press 2 sec: GO TERRAIN

Adjust the ground balance and
settings values



Capture of the ground effects
Press 2 sec: PINPOINT

3.5 plug: audio output jack

USB connection for charging
or updating the software

www.xpmetaldetectors.com